

OWNER: Oakland Baptist Church
DRILLER: Falwell Well Corporation
COUNTY: Bedford (Goode)

VDMR: 706
WWCR: 152
Depth: 120

SAMPLE DESCRIPTION
(washed)

0 - 10 Overburden - sand, white, yellow and brown, sub-angular, arkosic, with mica
10 - 20 as above
20 - 30 as above
30 - 40 as above
40 - 50 as above
50 - 60 as above
60 - 70 as above
70 - 80 Overburden - sand, white, tan and yellow, arkosic, mica flakes, traces of pyrite and biotite mica (Top of bedrock at bottom of this interval)
80 - 90 Granite - quartz, biotite and feldspar with traces of mica and pyrite
90 -100 as above
100 -110 as above
110 -120 as above

GEOLOGIC SUMMARY

<u>Age</u>	<u>Formation or Unit</u>
Pre-Cambrian	Lynchburg Formation

Division of Mineral Resources
Laurence H. Gardner II - Geologist
September 17, 1962