



OWNER: Rodger Barlow  
DRILLER: Sydnor Pump & Well Co.  
COUNTY: Rockingham (New Market)

VDMR # 879  
WWCR # 458  
TOTAL DEPTH : 138

GEOLOGIC LOG

0-20	No samples
20	Overburden - appears to be badly weathered calcareous siltstone.
30	Siltstone - locally shaly, light to dark gray, moderately hard, flaky, no apparent bedding to poorly fissile, calcareous and argillaceous with; common muscovite, and rare carbonaceous material.
45	As above
60	As above
75	As above
90	As above
105	As above
120	As above
135	As above

GEOLOGIC SUMMARY

<u>AGE</u>	<u>ROCK UNIT</u>
Ordovician	Martinsburg formation

Virginia Division of Mineral Resources  
John M. Wilson - Geologist  
October 4, 1963